

Oil Field Environmental Incident Summary

Incident: 20151029094815

Date/Time of Notice: 10/29/2015 09:48

Responsible Party: LIBERTY RESOURCES MANAGEMENT COMPANY, LLC

Well Operator: LIBERTY RESOURCES MANAGEMENT COMPANY, LLC

Well Name: RON BURGUNDY 3-23-14H

Field Name: TEMPLE

Well File #: 27334

Date Incident: 10/28/2015

Time Incident: 15:30

Facility ID Number:

County: WILLIAMS

Twp: 158

Rng: 96

Sec: 23

Qtr:

Location Description: Sill contained on location. Spill area was on location around the flare.

Submitted By: Tappan Souther

Received By:

Contact Person: Tappan Souther

1200 17TH STREET, SUITE 2200

DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Barrels	1	Barrels		

Brine

Other

Description of Other Released Contaminant:

1 BBL of produced oil.

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

None.

Areal Extent:

The 1 BBL of oil was contained on the wellsite near the flare area.

Potential Environmental Impacts:

None.

Action Taken or Planned:

The 1 BBL of oil was removed with a bucket loader.

Wastes Disposal Location: Local disposal.

Agencies Involved:

Updates

Date: 10/29/2015 ***Status:*** Reviewed - Assigned to Other Agency

Author: Souder, Taylor

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to equipment failure, remained on location according to the report. NDIC retains oversight.